

INSPECTION SHEET 検品書  
BULLDOZER ブルドーザー

INSPECTION DATE	2024/10/28	MAKE	KOMATSU	MODEL	D31PLL-20E
SERIAL	48482		STAMP	48482	
HR METER	6780	HR	SHOE	1050LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	<input checked="" type="radio"/> PS · DD	DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUT
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>BLADE &amp; CYLINDERS</b>		
BLADE	<input checked="" type="radio"/> FAIR · Attn	
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn	
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn	
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn	
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			1
<b>COMMENT</b>			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<input checked="" type="radio"/> FAIR · Attn		
EQUALIZER BAR	<input checked="" type="radio"/> FAIR · Attn		
<b>COMMENT</b>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。