

**INSPECTION SHEET 検品書**  
**CRAWLER CRANE クローラクレーン**

|                 |               |       |         |           |         |
|-----------------|---------------|-------|---------|-----------|---------|
| INSPECTION DATE | 2024/10/17    | MAKE  | KOMATSU | MODEL     | LC755-2 |
| SERIAL No.      | PLATE : 20101 | STAMP |         | NOT FOUND |         |
| HR METER        | 1745          | HR    | SHOE    | 450G PADS | YEAR YR |

|   |   |
|---|---|
| <b>ENGINE : MODEL 4D95LE-1 S/N 207106</b> |   |
| Oil leakage                               | <input checked="" type="radio"/> FAIR · Attn                            |
| Blow-By                                   | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound                                     | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil                                       | <input checked="" type="radio"/> FAIR · Attn                            |
| Exhaust Color                             | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>OPERATION PUMP</b>                     |   |
| Sound                                     | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil leakage                               | <input checked="" type="radio"/> FAIR · Attn                            |
| Power                                     | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>COOLING SYSTEM</b>                     |   |
| Radiator                                  | <input checked="" type="radio"/> FAIR · Attn                            |
| Oil Cooler                                | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>OPERATING SYSTEM</b>                   |   |
| Computer                                  | <input checked="" type="radio"/> OK · NG                                |
| Swing                                     | <input checked="" type="radio"/> FAIR · Attn                            |
| Travel                                    | <input checked="" type="radio"/> FAIR · Attn                            |
| <b>BOOM</b>                               |   |
| MAIN BOOM                                 |   |
| BOOM TOTAL                                |   |
| TOP SHEAVE                                | YES · <input checked="" type="radio"/> NO                               |
| JIB                                       |   |
| TOWER                                     |   |

|   |   |
|---|---|
| <b>INTERIOR See Photos. 写真参照</b>  |   |
| Operator's Seat   | <input checked="" type="radio"/> FAIR · Attn 破れあり HUGE CUTS         |
| Inside Cover  | <input checked="" type="radio"/> FAIR · Attn                        |
| Glasses   | <input checked="" type="radio"/> FAIR · Attn                        |
| AirCon  | A/C · H/C · <input checked="" type="radio"/> H only · C only · None |
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                                     |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                | 4   |
| <b>COMMENT</b>  |   |
| WEIGHT  | -   |
| HOOK  | 4.9t  |
| LIFTER  | YES · <input checked="" type="radio"/> NO                           |
| <b>COMMENT</b>  |   |
| CAB   |   |
| 5段ブーム 5-SECTION BOOM  |   |
| プレートもう1枚あり W/ANOTHER PLATE  |   |
| MAKE: MAEDA CC-505-C00123 (STAMP: C00123)                                   |   |
| <b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> |   |
| 3   |   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。