

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/4	MAKE	KOMATSU	MODEL	WA100-5
SERIAL	73300		STAMP	W108-73300	
HR METER	16249	HR	Odometer	58418	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	16.9-24	

ENGINE : MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	<input checked="" type="radio"/> YES · NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	<input checked="" type="radio"/> PS · DD
Transmission	<input checked="" type="radio"/> FAIR · Attn
Travel	<input checked="" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn
INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn 破れあり HUGE CUT
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	<input checked="" type="radio"/> FAIR · Attn *1
Bell crank	<input checked="" type="radio"/> FAIR · Attn
Bucket	<input checked="" type="radio"/> FAIR · Attn
Articulate	<input checked="" type="radio"/> FAIR · Attn ガタあり LOOSE

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
STEERING TYPE	<input checked="" type="radio"/> WHEEL STEERING / <input type="radio"/> COMMAND STEERING / <input type="radio"/> LEVER STEERING
RIDE CONTROL	YES · <input checked="" type="radio"/> NO
ATTACHMENTS	
STD BKT	<input checked="" type="radio"/> YES · OTHER
BLADE	YES · <input checked="" type="radio"/> NO Piping for Tilt YES · <input checked="" type="radio"/> NO
COMMENT	
*1 左側シリンダー油漏れ小、ロングアーム	
*1 LEFT CYLINDER: OIL LEAKING, LONG ARM	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。