

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/8	MAKE	HITACHI	MODEL	ZX17U-5A
SERIAL	HCMABAA0A00026949		STAMP	HCMABAA0A00026949	
HR METER	140	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	230R	

ENGINE : MODEL S/N

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM

Swing	FAIR	Attn	
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	Attn	
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
BKT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5
--------------------------------------------------------------	---

COMMENT

クローラー伸縮OK VARIABLE WIDTH UNDERCARRIAGE

BKT	STD	SLOPE / NARROW / SKELETON / OTHER ()	
-----	-----	------------------------------------------	--

Lever	LONG	WRIST	
-------	------	-------	--

Multi	MULTI	2 · NO	
-------	-------	--------	--

ARM-CRANE	YES	NO	
-----------	-----	----	--

BLADE	YES	NO	
-------	-----	----	--

OFFSET	YES	NO	
--------	-----	----	--

OFFSET Cylinder	FAIR	Attn	
-----------------	------	------	--

Piping	YES	NO	Breaker only · Multi
--------	-----	----	-----------------------------

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5
----------------------------------------------------------------------	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。