

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |  |      |         |            |         |
|-----------------|--|------|---------|------------|---------|
| INSPECTION DATE | 2024/10/9                              | MAKE | KOBELCO | MODEL      | SK200-8 |
| SERIAL          | YN12-62082                             |      | STAMP   | YN12-62082 |         |
| HR METER        | 5451                                   | HR   | YEAR    | YR         |         |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 600G       |         |

**ENGINE : MODEL** \_\_\_\_\_ **S/N** \_\_\_\_\_

|               |                 |                            |
|---------------|-----------------|----------------------------|
| Oil leakage   | FAIR · Attn     | _____                      |
| Blow-By       | FAIR · Attn     | A LITTLE · MIDDLE · SEVERE |
| Sound         | FAIR · Attn     | _____                      |
| Oil           | FAIR · Attn     | _____                      |
| Exhaust Color | FAIR · Attn     | _____                      |
| US EPA        | YES · <b>NO</b> | _____                      |

**MAIN PUMP**

|             |             |       |
|-------------|-------------|-------|
| Sound       | FAIR · Attn | _____ |
| Oil leakage | FAIR · Attn | _____ |
| Power       | FAIR · Attn | _____ |

**COOLING SYSTEM**

|            |             |       |
|------------|-------------|-------|
| Radiator   | FAIR · Attn | _____ |
| Oil Cooler | FAIR · Attn | _____ |

**OPERATING SYSTEM**

|        |             |       |
|--------|-------------|-------|
| Swing  | FAIR · Attn | _____ |
| Travel | FAIR · Attn | _____ |

**INTERIOR** See Photos. 写真参照

|                 |                                    |       |
|-----------------|------------------------------------|-------|
| Operator's Seat | FAIR · Attn                        | _____ |
| Inside Cover    | FAIR · Attn                        | _____ |
| Glasses         | FAIR · Attn                        | _____ |
| AirCon          | A/C · H/C · H only · C only · None | _____ |

**BOOM / ARM / BKT**

|               |             |            |
|---------------|-------------|------------|
| Boom          | FAIR · Attn | _____      |
| Boom Cylinder | FAIR · Attn | _____      |
| Arm           | FAIR · Attn | _____      |
| Arm Cylinder  | FAIR · Attn | _____      |
| BKT           | FAIR · Attn | ガタあり LOOSE |
| BKT Cylinder  | FAIR · Attn | _____      |

**UNDERCARRIAGE :** See Photos. 写真参照

|  |   |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--|---|

**COMMENT**

|   |
|---|
| <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> |
|---|

|     |   |
|-----|---|
| BKT | STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
|-----|---|

|       |              |
|-------|--------------|
| Lever | LONG · WRIST |
|-------|--------------|

|       |                |
|-------|----------------|
| Multi | MULTI · 2 · NO |
|-------|----------------|

|           |          |
|-----------|----------|
| ARM-CRANE | YES · NO |
|-----------|----------|

|       |          |
|-------|----------|
| BLADE | YES · NO |
|-------|----------|

|        |          |
|--------|----------|
| OFFSET | YES · NO |
|--------|----------|

|                 |             |
|-----------------|-------------|
| OFFSET Cylinder | FAIR · Attn |
|-----------------|-------------|

|        |          |                      |
|--------|----------|----------------------|
| Piping | YES · NO | Breaker only · Multi |
|--------|----------|----------------------|

**COMMENT**

|   |
|---|
| <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> <p>_____</p> |
|---|

|  |   |
|--|---|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|--|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。