

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/22	MAKE	KOBELCO	MODEL	SK200-8
SERIAL	YN12-57770		STAMP	YN12-57770	
HR METER	5742	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL			S/N		
Oil leakage	FAIR · Attn		UNDERCARRIAGE : See Photos. 写真参照		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
Sound	FAIR · Attn		COMMENT		
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			
MAIN PUMP			BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()	
Sound	FAIR · Attn		Lever	LONG · WRIST	
Oil leakage	FAIR · Attn		Multi	MULTI · 2 · NO	
Power	FAIR · Attn		ARM-CRANE	YES · NO	
COOLING SYSTEM			BLADE	YES · NO	
Radiator	FAIR · Attn		OFFSET	YES · NO	
Oil Cooler	FAIR · Attn		OFFSET Cylinder	FAIR · Attn	
OPERATING SYSTEM			Piping	YES · NO Breaker only · Multi	
Swing	FAIR · Attn		COMMENT		
Travel	FAIR · Attn			
INTERIOR See Photos. 写真参照				
Operator's Seat	FAIR · Attn	破れあり TORN		
Inside Cover	FAIR · Attn			
Glasses	FAIR · Attn			
AirCon	A/C · H/C · H only · C only · None			
BOOM / ARM / BKT				
Boom	FAIR · Attn			
Boom Cylinder	FAIR · Attn			
Arm	FAIR · Attn			
Arm Cylinder	FAIR · Attn			
BKT	FAIR · Attn	ピンガタあり PIN: LOOSE		
BKT Cylinder	FAIR · Attn		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。