

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/10/16	MAKE	HITACHI	MODEL	CX500-C
SERIAL No.	PLATE : 24D-2075	STAMP		243-2075	
HR METER	31550	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	*1
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 3, 6m × 2, 3m × 1	
BOOM TOTAL	52m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB	15m	
TOP, BOTTOM, 3m × 3		
TOWER		

INTERIOR		See Photos. 写真参照
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	右アームレスト破れあり RIGHT ARMREST: CUTS
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
WEIGHT		
		2
HOOK		
		50t, 30t, BALL
LIFTER		
		YES · <input checked="" type="radio"/> NO
COMMENT		
*1 コントローラ異常表示あり、ML未確認		
*1 WARNING DISPLAY FOR CONTROLLER, OPERATION: NOT CHECKED		
@NARITA YARD		
BOOM: TOP, BOTTOM, 9m × 1		
@SAKURA YARD		
BOOM: 9m × 2, 6m × 2, 3m × 1		
HOOK: 50t, BALL		
JIB: TOP, BOTTOM, 3m × 3		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。