

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

| | | | | | | | |
|-----------------|--|------|----------|-----------|----------|------|----|
| INSPECTION DATE | 2024/10/28 | MAKE | HITACHI | MODEL | ZW310-5B | | |
| SERIAL | BANNFAA0E90H10399 | | STAMP | 90H1-0399 | | | |
| HR METER | 17829 | HR | Odometer | 75305 | km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | | TIRE SIZE | 26.5R25 | | |

| ENGINE : MODEL | S/N |
|---------------------------|---|
| Oil leakage | FAIR · Attn |
| Blow-By | FAIR · Attn A LITTLE · MIDDLE · SEVERE |
| Sound | FAIR · Attn |
| Oil | FAIR · Attn |
| Exhaust Color | FAIR · Attn |
| US EPA | YES · NO |
| OPERATION PUMP | |
| Sound | FAIR · Attn |
| Oil leakage | FAIR · Attn |
| Power | FAIR · Attn |
| COOLING SYSTEM | |
| Radiator | FAIR · Attn |
| Oil Cooler | FAIR · Attn |
| TRANSMISSION & TRAVEL | |
| T/M TYPE | PS · DD |
| Transmission | FAIR · Attn |
| Travel | FAIR · Attn |
| FOOT BRAKE | FAIR · Attn |
| PARKING BRAKE | FAIR · Attn |
| INTERIOR See Photos. 写真参照 | |
| Operator's Seat | FAIR · Attn |
| Inside Cover | FAIR · Attn |
| Glasses | FAIR · Attn |
| AirCon | A/C · H/C · H only · C only · None |
| FRONT & CYLINDERS | |
| Arm | FAIR · Attn |
| Bell crank | FAIR · Attn |
| Bucket | FAIR · Attn |
| Articulate | FAIR · Attn |

| UNDERCARRIAGE : See Photos. 写真参照 | |
|--|---|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
| COMMENT | |
| | |
| | |
| | |
| | |
| | |
| STEERING TYPE | WHEEL STEERING / COMMAND STEERING / LEVER STEERING |
| RIDE CONTROL | YES · NO |
| ATTACHMENTS | |
| STD BKT | YES · OTHER |
| BLADE | YES · NO Piping for Tilt YES · NO |
| COMMENT | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。