

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/29	MAKE	KOMATSU	MODEL	PC200-7
SERIAL	205204		STAMP	KMTPC049T02205204	
HR METER	ERROR	HR	YEAR	2003	YR
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	
<b>MAIN PUMP</b>		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE
Travel	<u>FAIR</u> · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<u>FAIR</u> · Attn	破れあり TORN
Inside Cover	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	F枠サビ、腐食あり WINDSHIELD FRAME: CORRODED
AirCon	<u>A/C</u> · H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	ガタあり LOOSE
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON ( <u>OTHER</u> ) (MAGNET)
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	<u>YES</u> · NO *1
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · Multi *2
<b>COMMENT</b>	
MAGNET LECHX11F6-M110297	
マグネット動作未確認 OPERATION OF MAGNET: NOT CHECKED	
回転灯破損あり ROTARY LAMP: BROKEN	
整流機ボックス変形あり、開閉不可	
RECTIFIER BOX: DISTORTED, UNABLE TO OPEN or CLOSE	
発電機: 油脂類OK GENERATOR CONDITION: OK (4427HR)	
発電機用鍵欠、始動できない	
IGNITION KEY OF GENERATOR: MISSING, UNABLE TO START THE ENGINE	
制御盤不具合の書き残しあり	
NOTE FOR MALFUNCTION OF CONTROL PANEL	
*1 クレーンモード入らない CRANE MODE: UNABLE TO TURN ON	
*2 ペダル動作しない PEDAL: NOT WORKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。