INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/11	MAKE	CAT	MODEL	313DCR
SERIAL	CAT0313DCLCE01150			STAMP	CAT0313DCLCE01150
HR METER	4443 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	
Travel	FAIR・Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	ドア下部割れあり LOWER DOOR GLASS: BROKEN
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	右側サビあり RIGHT CYLINDER: RUSTY
Arm	FAIR・Attn	
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi
COMMENT		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。