

INSPECTION SHEET 検品書

DUMP TRUCK ダンプ

INSPECTION DATE	2026/1/8	CATEGORY	ON-ROAD DUMP	OFF-ROAD DUMP
MAKE	CAT		MODEL	771D
SERIAL	6YS00215		STAMP	6YS00215
HR METER	42115	HR	ODOMETER	km
TIRE SIZE	18.00R33		YEAR	YR

ENGINE : MODEL S/N			MAIN FRAME	
Oil leakage	FAIR	Attn	MAIN FLAME	FAIR Attn
Blow-By	FAIR	Attn	VESSEL	
Sound	FAIR	Attn	MAKE	
Oil	FAIR	Attn	VESSEL	FAIR Attn *1
Exhaust Color	FAIR	Attn	REAR GATE TYPE	NORMAL L-GATE (FLAT)
US EPA	YES	NO	REAR GATE	FAIR Attn
OPERATION PUMP				
Sound	FAIR	Attn	UNDERCARRIAGE: See Photos. 写真参照	
Oil leakage	FAIR	Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
油漏れあり OIL LEAKING			3	
Power	FAIR	Attn	TIRE WEAR FAIR WORN UNEVEN WEAR	
COOLING SYSTEM				
Radiator	FAIR	Attn	COMMENT	
Oil Cooler	FAIR	Attn	ROPS-CAB	
TRANSMISSION & TRAVEL				
T/M TYPE	AT	MT	作動油タンク油漏れ小 HYDRAULIC OIL TANK: OIL LEAKING	
Transmission	FAIR	Attn	ステアリング周りホースからエアー漏れあり	
4WD	4WD	2WD	SOME HOSE AROUND STEERING: AIR LEAKING	
Travel	FAIR	Attn	付属品:ステップ、ミラー等部材、タイヤ2本	
Articulate	FAIR	Attn	STEP, MIRROR, SOME PARTS, & 2 PIECES OF TIRES AS SPARE	
FOOT BRAKE	FAIR	Attn	*1 右Rベッセル用シリンダー油汚れあり RIGHT CYLINDER: OIL STAINS	
PARKING BRAKE	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only C only None	RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)
				3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。