

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/10/29	MAKE	CAT	MODEL	910H
SERIAL	CAT0910HJSAT00816			STAMP	CAT0910HJSAT00816
HR METER	ERROR	HR	Odometer	874	km YEAR YR
CAB/CNP	<input checked="" type="checkbox"/> ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL C4.4 S/N C4E09831	
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn
Blow-By	<input checked="" type="checkbox"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="checkbox"/> FAIR · Attn
Oil	<input checked="" type="checkbox"/> FAIR · Attn
Exhaust Color	<input checked="" type="checkbox"/> FAIR · Attn
US EPA	<input checked="" type="checkbox"/> YES · NO
<b>OPERATION PUMP</b>	
Sound	<input checked="" type="checkbox"/> FAIR · Attn
Oil leakage	<input checked="" type="checkbox"/> FAIR · Attn
Power	<input checked="" type="checkbox"/> FAIR · Attn
<b>COOLING SYSTEM</b>	
Radiator	<input checked="" type="checkbox"/> FAIR · Attn
Oil Cooler	<input checked="" type="checkbox"/> FAIR · Attn
<b>TRANSMISSION &amp; TRAVEL</b>	
T/M TYPE	<input checked="" type="checkbox"/> PS · DD
Transmission	<input checked="" type="checkbox"/> FAIR · Attn
Travel	<input checked="" type="checkbox"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="checkbox"/> FAIR · Attn ブレーキペダル動作重い BRAKE PEDAL: HEAVY
PARKING BRAKE	<input checked="" type="checkbox"/> FAIR · Attn
<b>INTERIOR See Photos. 写真参照</b>	
Operator's Seat	<input checked="" type="checkbox"/> FAIR · Attn
Inside Cover	<input checked="" type="checkbox"/> FAIR · Attn
Glasses	<input checked="" type="checkbox"/> FAIR · <input checked="" type="checkbox"/> Attn *1
AirCon	A/C · <input checked="" type="checkbox"/> H/C · H only · C only · None
<b>FRONT &amp; CYLINDERS</b>	
Arm	<input checked="" type="checkbox"/> FAIR · <input checked="" type="checkbox"/> Attn 右シリンダーサビあり RIGHT CYLINDER: RUSTY
Bell crank	<input checked="" type="checkbox"/> FAIR · Attn
Bucket	<input checked="" type="checkbox"/> FAIR · Attn
Articulate	<input checked="" type="checkbox"/> FAIR · Attn ガタあり LOOSE

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
STAIRING TYPE <input checked="" type="checkbox"/> WHEEL STEERING / <input type="checkbox"/> COMMAND STEERING / <input type="checkbox"/> LEVER STEERING	
RIDE CONTROL	YES · <input checked="" type="checkbox"/> NO
<b>ATTACHMENTS</b>	
STD BKT	<input checked="" type="checkbox"/> YES · OTHER
BLADE	YES · <input checked="" type="checkbox"/> NO Piping for Tilt <input checked="" type="checkbox"/> YES · NO
<b>COMMENT</b>	
ワンタッチ付 W/ONE-TOUCH	
E/Gフード左側ダンパー破損あり LEFT ENGINE HOOD DAMPER: BROKEN	
右サイドカバーヒンジ破損あり SOME RIGHT SIDE COVER HINGE: BROKEN	
*1 F左右割れあり BOTH SIDE OF WINDSHIELD: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。