

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2024/10/24	MAKE	KOBELCO	MODEL	7055-2
SERIAL No.	PLATE : GB01166		STAMP	01166	
HR METER	11898	HR	SHOE	760FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	ML未確認 ML: NOT CHECKED
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 9m × 1, 6m × 2, 3m × 2	
BOOM TOTAL	36m	
TOP SHEAVE	<input checked="" type="radio"/> YES · NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
Operator's Seat	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	破れあり HUGE CUT
Inside Cover	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
WEIGHT 2		
HOOK		55t, LIGHT HOOK
LIFTER		YES · <input checked="" type="radio"/> NO
COMMENT		
ガントリーシリンダーロッド腐食あり GANTRY CYLINDER RODS: CORRODED		
CAB下部腐食大 BOTTOM OF CAB: MUCH CORRODED		
*1 コア上部潰れあり UPPER PART OF CORE: DEFORMED		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1		55t HOOK
@SAKURA No.2 YARD		
BOOM: 9m × 1, 6m × 1, 3m × 2		LIGHT HOOK
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。