

INSPECTION SHEET 検品書  
OTHER その他

|                 |  |          |                         |            |      |      |    |
|-----------------|--|----------|-------------------------|------------|------|------|----|
| INSPECTION DATE | 2024/10/16                             | CATEGORY | 自走式パイルドライバー PILE DRIVER |            |      |      |    |
| MAKE            | NISSHA                                 |          | MODEL                   | DH558-110M |      |      |    |
| SERIAL          | S55115                                 |          | STAMP                   | NOT FOUND  |      |      |    |
| HR METER        | 4952                                   | HR       | Odometer                | km         | YEAR | 1998 | YR |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |          | SHOE                    | 800FLAT    | TIRE |      |    |

| ENGINE      | MODEL       | S/N  |
|-------------|-------------|--|
| Oil leakage | FAIR · Attn | Oil FAIR · Attn                                      |
| Blow-By     | FAIR · Attn | A LITTLE · MIDDLE · SEVERE Exhaust Color FAIR · Attn |
| Sound       | FAIR · Attn | EPA YES · NO   |

|                            |             |
|----------------------------|-------------|
| CONDITION                  | FAIR · Attn |
| 未確認 OPERATION: NOT CHECKED |             |

|  |   |  |
|--|---|--|
| UNDERCARRIAGE : See Photos. 写真参照   |   |  |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                       | 2 |  |
| COMMENT  |   |  |
| シート破れあり SEAT: TORN   |   |  |
| A/C  |   |  |
| 右Fアウトリガー油漏れ小、左右Rアウトリガー油漏れ大 FRONT RIGHT OUTRIGGER: OIL LEAKING, REAR OUTRIGGERS: SEVERE OIL LEAKING |   |  |
| 旋回流れ大(逆転しないと止まらない) SWING: MUCH DRIFTED (NEED TO OPERATE TO SWING OPPOSITE SIDE TO STOP)            |   |  |
| F配管周り油漏れ大(ワンタッチカプラ外し) AROUND FRONT PIPING: SEVERE OIL LEAKING (ONE-TOUCH: COME OFF)                |   |  |
| ブザー鳴りっぱなし(バッテリーマイナスターミナル外し) WARNING SOUNDS: ON (BATTERY NEGATIVE TERMINAL: COME OFF)               |   |  |
| @SAKURA No.2 YARD  |   |  |
| LEADER (33m), LEADER TOP, BACKSTAY, WEIGHT × 2   |   |  |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                               | 2 |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。