

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/10/17	MAKE	KOMATSU	MODEL	PC30MR-2
SERIAL	23800	STAMP	KMTPC095C05023800		
HR METER	1078	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / (ROPS CNP) / CNP / NONE		SHOE	300G PADS	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	(YES) · NO	
<b>MAIN PUMP</b>		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
<b>COOLING SYSTEM</b>		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
<b>OPERATING SYSTEM</b>		
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE
Travel	(FAIR) · (Attn)	右足遅い RIGHT TRACK: SLOW
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	(FAIR) · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
<b>BOOM / ARM / BKT</b>		
Boom	(FAIR) · Attn	スイングガタあり SWING: LOOSE
Boom Cylinder	(FAIR) · Attn	
Arm	(FAIR) · Attn	
Arm Cylinder	(FAIR) · Attn	
BKT	(FAIR) · Attn	
BKT Cylinder	(FAIR) · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER( )
Lever	LONG · (WRIST)
Multi	(MULTI) · 2 · NO
ARM-CRANE	YES · (NO)
BLADE	(YES) · NO
OFFSET	YES · (NO)
OFFSET Cylinder	FAIR · Attn
Piping	YES · (NO) Breaker only · Multi
<b>COMMENT</b>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。