

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2024/10/29	MAKE	KUBOTA	MODEL	U-30-6A
SERIAL	KBCCZ69APL3G10107		STAMP	KBCCZ69APL3G10107	
HR METER	526	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300G PADS	

<b>ENGINE : MODEL</b>		S/N	7LM2491
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		

<b>MAIN PUMP</b>	
Sound	<u>FAIR</u> · Attn
Oil leakage	<u>FAIR</u> · Attn
Power	<u>FAIR</u> · Attn

<b>COOLING SYSTEM</b>	
Radiator	<u>FAIR</u> · Attn
Oil Cooler	<u>FAIR</u> · Attn

<b>OPERATING SYSTEM</b>	
Swing	<u>FAIR</u> · Attn
Travel	<u>FAIR</u> · Attn

<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	<u>FAIR</u> · Attn 破れあり CUTS
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · <u>None</u>

<b>BOOM / ARM / BKT</b>	
Boom	<u>FAIR</u> · Attn
Boom Cylinder	<u>FAIR</u> · Attn
Arm	<u>FAIR</u> · Attn
Arm Cylinder	<u>FAIR</u> · Attn
BKT	<u>FAIR</u> · Attn
BKT Cylinder	<u>FAIR</u> · Attn

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

<b>COMMENT</b>	

BKT	STD · <u>SLOPE</u> · NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	MULTI · <u>2</u> · NO
ARM-CRANE	<u>YES</u> · NO
BLADE	<u>YES</u> · NO
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	FAIR · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u>

<b>COMMENT</b>	
登録キーあり W/REGISTERING KEY	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。