INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2024/10/29 N			KE	MOROOK		MODEL	MST-300VDR			
SERIAL	4375			5	•	STAMP			4375			
HR METER	149 HR Odomete			-			m YEAR			YR		
CAB/CNP	ROPS CA	AB / C	AB / ROP	S CNP	NON (PIN)	IE SHOE		350R	TIRE			
ENGINE : MODEL S/N						MAIN FRAME						
Oil leakage	leakage FAIR · Attn						MAIN FLAME FAIR - Attn					
Blow-By	FAIR · Attn	A LITTI	LE · MIDDL	E · SEV	ERE	VESSEL						
Sound	FAIR · Attn					VESSE	EL	FAIR • Attn	ベッセル旋回	しない UNABLE TO) SWING	
Oil	FAIR · Attn					REAR GATE	TYPE	NORMA	L • L-	-GATE (FLAT)		
Exhaust Color	FAIR · Attn					REAR G	ATE	FAIR • Attn				
US EPA	YES) · NO					UNDERCARRIAGE: See Photos. 写真参照						
OPERATION PUMP						RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3						
Sound	FAIR · Attn					COMMEN	Γ					
Oil leakage	FAIR · Attn					ベッセル上	下&旅	回レバー原	見り悪い			
Power	FAIR · Attn					OPERATIO)N LE	VER FOR V	/ESSEL: F	IARD TO RET	URN	
COOLING SYSTEM												
Radiator	FAIR · Attn											
Oil Cooler	FAIR · Attn											
TRANSMIS												
T/M TYPE	PS) · DD			No. OF GEARS	2 GEARS	5						
Transmission	FAIR · Attn											
Travel	FAIR · Attn											
Swing	FAIR · Attn											
Articulate	FAIR · Attn											
FOOT BRAKE	FAIR · Attn											
PARKING BRAKE	FAIR · Attn											
INTERIOR See Photos. 写真参照												
Operator's Seat	FAIR · Attn											
Inside Cover	FAIR · Attn											
Glasses	FAIR · Attn											
AirCon	A/C ·	H/C	 H only 	 C only 	None	RUST of BODY	(5: NONE	, 4: A LITTLE, 3:	MIDDLE, 2: MU	CH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。