INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/25	MAKE	TADANO	MODEL	GR-600N-1
SERIAL No.	PLATE : FD5256			STAMP :	TR600-0256
HR METER	13734 HR			Odometer	71591 km
TIRE SIZE	505/95R25			YEAR	YR

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
OPERATION PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Computer	OK・NG	
Swing	FAIR・Attn	
Travel	FAIR・Attn	
TRANSMISSION		
Transmission	FAIR・Attn	
No. OF GEARS	4 GEARS	
No, of DRIVE WHEELS	4 WD	
INTERIOR	See Photos. 写真参照	
Operator's Seat	FAIR・Attn	切れあり HUGE CUT
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	

COMMENT

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	FAIR・Attn	
DERRICKING CYL.	FAIR・Attn	
EXTENSION CYL.	FAIR・Attn	
JIB	YES・NO	
JIB TYPE	STD・PWR	
MAIN & SUB WIRE	YES・NO	
HOOK	60t, 25t, BALL	
UNDERCARRIAGE :	See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		4

COMMENT

OUTRIGGERS		
OUTRIGGERS	X・H	
OUTRIGGERS COND.	FAIR・Attn	*1

COMMENT

*1 右F縦シリンダーにじみあり FRONT RIGHT VERTICAL CYLINDER: OIL OOZING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。