

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/10/28	MAKE	TADANO	MODEL	TR-350M-3
SERIAL No.	PLATE :	506032	STAMP :	TR352-0031	
HR METER	6205	HR	Odometer	16870	km
TIRE SIZE	445/95R25	YEAR	YR		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	CPUエラー表示あり CPU ERROR DISPLAY
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input type="radio"/> FAIR · Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C	H/C · H only · C only · None
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	5 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · Attn
EXTENSION CYL.	<input type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	20t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
<b>COMMENT</b>	
シングルトップ欠 SINGLE TOP: MISSING	
35tフック欠 35t HOOK: MISSING	
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。