

**INSPECTION SHEET 検品書**  
**ROUGH TERRAIN CRANE ラフタークレーン**

INSPECTION DATE	2024/10/29	MAKE	TADANO	MODEL	TR-500M-3
SERIAL No.	PLATE : 581567		STAMP : TR551-0120		
HR METER	91 + 5749	HR	Odometer	325 + 42194	km
TIRE SIZE	505/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn	A LITTLE · <input checked="" type="radio"/> MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	OK · <input checked="" type="radio"/> NG *1	
Swing	<input type="radio"/> FAIR · Attn	
Travel	<input type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input type="radio"/> FAIR · Attn	
No. OF GEARS	4	GEARS
No. of DRIVE WHEELS	4	WD
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input type="radio"/> FAIR · Attn	
Inside Cover	<input type="radio"/> FAIR · <input type="radio"/> Attn	ドア内張り破れあり INSIDE COVER OF DOOR: CUTS
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>	
No. of Section	4 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · Attn
EXTENSION CYL.	<input type="radio"/> FAIR · Attn
JIB	YES · <input checked="" type="radio"/> NO
JIB TYPE	STD · PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	50t, 25t, BALL
<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
<b>OUTRIGGERS</b>	
OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
<b>COMMENT</b>	
CAB下エア一漏れ大 BOTTOM OF CAB: MUCH AIR LEAKING	
*1 ブーム全縮検知異常あり HOUSING SENSOR OF BOOM: MALFUNCTION	
<b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。