

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/24	MAKE	KOMATSU	MODEL	PC120-8NM
SERIAL	86363		STAMP	KMTPC202A01086363	
HR METER	15521	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油漏れ小 OIL LEAKING
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	*1
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
トラックローラー不良 SOME TRACK ROLLERS: MALFUNCTION	
BKT	STD / SLOPE / NARROW / SKELETON (OTHER)
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
アタッチメント: フェラーバンチャー ATTACHMENT: FELLING BUNCHER	
MAKE: MATSUMOTO MSE-45FGZX-12562	
アタッチメント: カッター不良	
CUTTER OF FELLING BUNCHER: MALFUNCTION	
ウインチ付 (動作OK) OPERATION OF WINCH: OK	
MAKE: NANSEI PWF-25-113-2059	
コントロールバルブ周り下の低板油漏れ跡あり	
UNDER COVER OF AROUND CONTROL VALVE: OIL LEAKED TRACE	
CABドアラッチ不良 DOOR LATCH: MALFUNCTION	
付属品: スタンダードバケット STANDARD BUCKET AS SPARE	
*1 プレーキ甘い、ガタあり BRAKE: LOOSE, SWING: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。