

INSPECTION SHEET 検品書  
WHEEL EXCAVATOR タイヤバックホー

|                 |  |      |           |            |         |
|-----------------|--|------|-----------|------------|---------|
| INSPECTION DATE | 2024/10/28                             | MAKE | SUMITOMO  | MODEL      | SW350-3 |
| SERIAL          | 350W3-5010                             |      | STAMP     | 350W3-5010 |         |
| HR METER        | 15612                                  | HR   | Odometer  | -          | km      |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | TIRE SIZE | 12.00-24   |         |
|                 |  |      | YEAR      | YR         |         |

|                                  |   |   |
|----------------------------------|---|---|
| <b>ENGINE : MODEL</b>            |   | <b>S/N</b>  |
| Oil leakage                      | FAIR · <input checked="" type="radio"/> Attn                        | 油汚れ大 MUCH OIL STAINS                                      |
| Blow-By                          | FAIR · <input checked="" type="radio"/> Attn                        | A LITTLE <input checked="" type="radio"/> MIDDLE · SEVERE |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Oil                              | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Exhaust Color                    | <input checked="" type="radio"/> FAIR · Attn                        |   |
| US EPA                           | YES · <input checked="" type="radio"/> NO                           |   |
| <b>MAIN PUMP</b>                 |   |   |
| Sound                            | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Oil leakage                      | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Power                            | <input checked="" type="radio"/> FAIR · Attn                        |   |
| <b>COOLING SYSTEM</b>            |   |   |
| Radiator                         | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Oil Cooler                       | <input checked="" type="radio"/> FAIR · Attn                        |   |
| <b>OPERATING SYSTEM</b>          |   |   |
| Swing                            | FAIR · <input checked="" type="radio"/> Attn                        | ガタあり SWING: LOOSE   |
| Travel                           | <input checked="" type="radio"/> FAIR · Attn                        |   |
| <b>INTERIOR See Photos. 写真参照</b> |   |   |
| Operator's Seat                  | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Inside Cover                     | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Glasses                          | <input checked="" type="radio"/> FAIR · Attn                        |   |
| AirCon                           | <input checked="" type="radio"/> A/C · H/C · H only · C only · None |   |
| <b>BOOM / ARM / BKT</b>          |   |   |
| Boom                             | FAIR · <input checked="" type="radio"/> Attn                        | パッチあり PATCHED   |
| Boom Cylinder                    | FAIR · <input checked="" type="radio"/> Attn                        | 左油漏れ小 LEFT CYLINDER: OIL LEAKING                          |
| Arm                              | <input checked="" type="radio"/> FAIR · Attn                        |   |
| Arm Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |   |
| BKT                              | <input checked="" type="radio"/> FAIR · Attn                        |   |
| BKT Cylinder                     | <input checked="" type="radio"/> FAIR · Attn                        |   |

|  |   |
|--|---|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                              |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3   |
| <b>COMMENT</b>   |   |
| 右Fホイール変形あり FRONT RIGHT RIM: PARTLY DEFORMED                          |   |
| BKT  | STD / SLOPE / NARROW / SKELETON / OTHER( )  |
| Lever  | LONG · <input checked="" type="radio"/> WRIST   |
| Multi  | MULTI · 2 · <input checked="" type="radio"/> NO   |
| ARM-CRANE  | YES · <input checked="" type="radio"/> NO   |
| BLADE  | YES · <input checked="" type="radio"/> NO   |
| OFFSET   | YES · <input checked="" type="radio"/> NO   |
| OFFSET Cylinder  | FAIR · Attn   |
| Piping   | <input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi 5 |
| OUTRIGGERS COND.   | FAIR · <input checked="" type="radio"/> Attn *1   |
| <b>COMMENT</b>   |   |
| エレベータCAB ELEVATOR CAB  |   |
| E/G下低板油汚れ大 COVER UNDER ENGINE: MUCH OIL STAINS                       |   |
| ロングブーム(作業半径:13.0m) LONG BOOM (OPERATION RADIUS: 13.0m)               |   |
| アタッチメントなし WITHOUT ATTACHMENT   |   |
| 付属品: オレンジピールグラブ(ピン欠)   |   |
| ORANGE PEEL GRAPPLE AS SPARE (PIN: MISSING)                          |   |
| MAKE: NANSEI BHS40JR-2-5073514                                       |   |
| *1 左R油圧抜けあり(自然降下あり)  |   |
| *1 REAR LEFT CYLINDER: HYDRAULIC DRIFT                               |   |
| オレンジピールバケット動作未確認   |   |
| OPERATION OF ORANGE PEEL GRAPPLE NOT CHECKED                         |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。