

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/12/12	MAKE	KOMATSU	MODEL	PC45R-8
SERIAL	5170		STAMP	5170	
HR METER	6305	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	400G	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · <u>Attn</u>	ポンプ周り油漏れ小 AROUND PUMP: OIL LEAKING
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<u>FAIR</u> · <u>Attn</u>	座面破損あり BROKEN
Inside Cover	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · <u>Attn</u>	ガタあり LOOSE
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	ブレーカーアーム BREAKER ARM
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG · <u>WRIST</u>
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO *1
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
ウインチ/ブレーカー切り替えバルブホース周り油漏れ小	
AROUND WINCH/BREAKER SWITCH VAVLE HOSES: OIL LEAKING	
ウインチ付 W/WINCH	
*1 下降側レバー固着気味	
*1 LEVER: A LITTLE STUCK FOR DOWN SIDE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。