

**INSPECTION SHEET 検品書  
EXCAVATOR バックホー**

INSPECTION DATE	2024/12/6	MAKE	HITACHI	MODEL	ZX225USRK-5B
SERIAL	HCMDCQA2E00305067		STAMP	HCMDCQA2E00305067	
HR METER	11559	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b>	4HK1	<b>S/N</b>	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	<input checked="" type="radio"/> YES · NO		
<b>MAIN PUMP</b>			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	油漏れ小 OIL LEAKING	
Power	<input checked="" type="radio"/> FAIR · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
<b>OPERATING SYSTEM</b>			
Swing	<input checked="" type="radio"/> FAIR · Attn	ガタ、流れあり SWING: LOOSE, DRIFTED	
Travel	<input checked="" type="radio"/> FAIR · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり TORN	
Inside Cover	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None		
<b>BOOM / ARM / BKT</b>			
Boom	<input checked="" type="radio"/> FAIR · Attn		
Boom Cylinder	<input checked="" type="radio"/> FAIR · Attn		
Arm	<input checked="" type="radio"/> FAIR · Attn		
Arm Cylinder	<input checked="" type="radio"/> FAIR · Attn		
BKT	<input checked="" type="radio"/> FAIR · Attn		
BKT Cylinder	<input checked="" type="radio"/> FAIR · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	<input checked="" type="radio"/> STD / <input type="radio"/> SLOPE / <input type="radio"/> NARROW / <input type="radio"/> SKELETON / OTHER ( )
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
<b>COMMENT</b>	
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING	
アタッチメントなし WITHOUT ATTACHMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。