

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/11/13	MAKE	KOMATSU	MODEL	PC10UU-3
SERIAL	10159	STAMP	10159		
HR METER	2556	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	180R	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · <u>Attn</u>	排気音あり EXHAUST SOUNDS
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
OPERATING SYSTEM		
Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	<u>FAIR</u> · Attn	
Inside Cover	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
BOOM / ARM / BKT		
Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · <u>Attn</u>	油漏れあり OIL LEAKING
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	<u>FAIR</u> · Attn	
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	<u>LONG</u> · WRIST
Multi	MULTI · 2 · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	<u>YES</u> · NO
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。