INSPECTION SHEET 検品書 EXCAVATOR パックホー

			L/(O/(1/()	. •	* * * * * * * * * * * * * * * * * * * *				
INSPECTION DATE		2024/9/24 MAKE F		KOMATSU	N	10DEL	PC200LC-8N1		
SERIAL	358034		-		STAMP	STAMP KMTPC197		PC197P02358034	
HR METER	R METER 6004 H		₹	YEAR		YR			
CAB/CNP ROPS CAB / CAB / ROPS CNP / CNP / NONE				NONE	SHOE	700G			
ENGINE :	MODEL	S/N			UNDERCA	RRIAGE	: See	Photos. 写真参照	
Oil leakage	FAIR · Attn				RUST (5: NON	IE, 4: A LITT	LE, 3: MIDD	LE, 2: MUCH, 1: CORRODED)	3
Blow-By	FAIR · Attn	A LITTLE · MIDDLE •	SEVERE		COMMENT	Γ			
Sound	FAIR · Attn								
Oil	FAIR · Attn								
Exhaust Color	FAIR · Attn								
US EPA	YES · NO								
MAIN PUMP					вкт (STD /SLO	PE / NARRO	OW / SKELETON / OTHER()
Sound	FAIR · Attn				Lever	LONG •	WRIST		
Oil leakage	FAIR · Attn				Multi	MULTI (•	2) NO		
Power	FAIR · Attn				ARM-CRANE	YES • (NC			
COOLING SYSTEM					BLADE	YES • (NC			
Radiator	FAIR · Attn				OFFSET	YES • (NC			
Oil Cooler	FAIR · Attn				OFFSET Cylinder	FAIR • Att	n		
OPERATING SYSTEM					Piping	YES • (NC	Breaker	only • Multi	
Swing FAIR・Attn 流れ小、ガタ小 SWING: A LITTLE DRIFTED, LOOSE				OSE	COMMENT				
Travel	FAIR · Attn				17.6mスー	パーロン	グ 17.6n	n SUPER LONG	
INTERIOR	See	Photos. 写真参照							
Operator's Seat	FAIR · Attn								
Inside Cover	FAIR · Attn								
Glasses	FAIR · Attn								
AirCon	A/C).	H/C • H only •	C only • No	ne					
BOOM / ARM / BKT									
Boom	FAIR · Attn								
Boom Cylinder	FAIR · Attn								
Arm	FAIR · Attn	補強あり REINFORCE	ED .						
Arm Cylinder	FAIR · Attn								

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)

BKT

BKT Cylinder FAIR · Attn

FAIR) · Attn