

INSPECTION SHEET 検品書  
OTHER その他

INSPECTION DATE	2024/11/19	CATEGORY	地盤改良機 GROUND IMPROVEMENT MACHINE			
MAKE	YBM		MODEL	GI-50C		
SERIAL	167		STAMP	NOT FOUND		
HR METER	4887	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB	<input checked="" type="radio"/> CAB	ROPS CNP / CNP / NONE	SHOE	400R	TIRE

ENGINE	MODEL	S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	Oil <input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
		Exhaust Color <input checked="" type="radio"/> FAIR · Attn
Sound	<input checked="" type="radio"/> FAIR · Attn	EPA YES · <input checked="" type="radio"/> NO

CONDITION	<input checked="" type="radio"/> FAIR · Attn
-----------	--

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

COMMENT

トラックフレーム石灰付着あり TRACK FRAMES: LIME STAINS

オーガ欠品 AUGER: MISSING

機体プレート BODY PLATE: IHI 55N2-WP000637

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。