

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2024/11/20	MAKE	MAEDA	MODEL	HF070R-2
SERIAL No.	PLATE : 7NU20403			STAMP : 7NU20403	
HR METER	3543	HR	Odometer	km	YEAR YR
CHASSIS	MODEL -			No. -	
SHOE	230R			TIRE SIZE	
MAX HIGHT	6.8 m			MAX WEIGHT 150 kg	

ENGINE : MODEL D722 S/N 7J4345	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Blow-By	<input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil	<input checked="" type="radio"/> FAIR · Attn
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn
US EPA	YES <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	<input checked="" type="radio"/> FAIR · Attn
Oil leakage	<input checked="" type="radio"/> FAIR · Attn
Power	<input checked="" type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input checked="" type="radio"/> FAIR · Attn
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT · MT No. OF GEARS GEARS
Transmission	<input checked="" type="radio"/> FAIR · Attn
4WD	4WD · 2WD
Travel	<input checked="" type="radio"/> FAIR · Attn
Swing	<input checked="" type="radio"/> FAIR · Attn
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn
BOOM	
No. of Section	2 SECTIONS
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · Attn

INTERIOR See Photos. 写真参照	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn
Inside Cover	<input checked="" type="radio"/> FAIR · Attn
Glasses	<input checked="" type="radio"/> FAIR · Attn
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
<p>OUTRIGGERS X · H</p> <p>OUTRIGGERS COND. <input checked="" type="radio"/> FAIR · Attn</p> <p>COMMENT</p> <p>機体外装リペイントあり REPAINTED</p> <p>*1 第2ブームシリンダーサビあり CYLINDER OF 2nd BOOM: RUSTY</p>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。