

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/12/2	MAKE	KOBELCO	MODEL	LK40Z
SERIAL	RW02-00803		STAMP	RW02-00803	
HR METER	3555	HR	Odometer	-	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		TIRE SIZE	12.5/70-16 6PR	

<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">ENGINE : MODEL</td> <td>S/N</td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Blow-By</td> <td><u>FAIR</u> · Attn</td> <td>A LITTLE · MIDDLE · SEVERE</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Oil</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Exhaust Color</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>US EPA</td> <td>YES · <u>NO</u></td> <td></td> </tr> <tr> <td colspan="3">OPERATION PUMP</td> </tr> <tr> <td>Sound</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Oil leakage</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Power</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td colspan="3">COOLING SYSTEM</td> </tr> <tr> <td>Radiator</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Oil Cooler</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td colspan="3">TRANSMISSION & TRAVEL</td> </tr> <tr> <td>T/M TYPE</td> <td><u>PS</u> · DD</td> <td></td> </tr> <tr> <td>Transmission</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Travel</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>FOOT BRAKE</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>PARKING BRAKE</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td colspan="3">INTERIOR See Photos. 写真参照</td> </tr> <tr> <td>Operator's Seat</td> <td><u>FAIR</u> · <u>Attn</u></td> <td>破れあり CUTS</td> </tr> <tr> <td>Inside Cover</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Glasses</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>AirCon</td> <td>A/C · H/C · H only · C only · <u>None</u></td> <td></td> </tr> <tr> <td colspan="3">FRONT & CYLINDERS</td> </tr> <tr> <td>Arm</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Bell crank</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Bucket</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> <tr> <td>Articulate</td> <td><u>FAIR</u> · Attn</td> <td></td> </tr> </table>	ENGINE : MODEL		S/N	Oil leakage	<u>FAIR</u> · Attn		Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	Sound	<u>FAIR</u> · Attn		Oil	<u>FAIR</u> · Attn		Exhaust Color	<u>FAIR</u> · Attn		US EPA	YES · <u>NO</u>		OPERATION PUMP			Sound	<u>FAIR</u> · Attn		Oil leakage	<u>FAIR</u> · Attn		Power	<u>FAIR</u> · Attn		COOLING SYSTEM			Radiator	<u>FAIR</u> · Attn		Oil Cooler	<u>FAIR</u> · Attn		TRANSMISSION & TRAVEL			T/M TYPE	<u>PS</u> · DD		Transmission	<u>FAIR</u> · Attn		Travel	<u>FAIR</u> · Attn		FOOT BRAKE	<u>FAIR</u> · Attn		PARKING BRAKE	<u>FAIR</u> · Attn		INTERIOR See Photos. 写真参照			Operator's Seat	<u>FAIR</u> · <u>Attn</u>	破れあり CUTS	Inside Cover	<u>FAIR</u> · Attn		Glasses	<u>FAIR</u> · Attn		AirCon	A/C · H/C · H only · C only · <u>None</u>		FRONT & CYLINDERS			Arm	<u>FAIR</u> · Attn		Bell crank	<u>FAIR</u> · Attn		Bucket	<u>FAIR</u> · Attn		Articulate	<u>FAIR</u> · Attn		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td colspan="2">UNDERCARRIAGE : See Photos. 写真参照</td> </tr> <tr> <td>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">2</td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> <div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING </div> <div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> RIDE CONTROL YES · <u>NO</u> </div> </td> </tr> <tr> <td colspan="2">ATTACHMENTS</td> </tr> <tr> <td>STD BKT</td> <td><u>YES</u> · OTHER</td> </tr> <tr> <td>BLADE</td> <td>YES · <u>NO</u> Piping for Tilt YES · <u>NO</u></td> </tr> <tr> <td colspan="2">COMMENT</td> </tr> <tr> <td colspan="2" style="height: 100px;"> 左昇降ステップ変形あり LEFT STEP: DEFORMED </td> </tr> <tr> <td>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</td> <td style="text-align: center;">2</td> </tr> </table>	UNDERCARRIAGE : See Photos. 写真参照		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	COMMENT		<div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING </div> <div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> RIDE CONTROL YES · <u>NO</u> </div>		ATTACHMENTS		STD BKT	<u>YES</u> · OTHER	BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>	COMMENT		左昇降ステップ変形あり LEFT STEP: DEFORMED		RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
ENGINE : MODEL		S/N																																																																																																													
Oil leakage	<u>FAIR</u> · Attn																																																																																																														
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE																																																																																																													
Sound	<u>FAIR</u> · Attn																																																																																																														
Oil	<u>FAIR</u> · Attn																																																																																																														
Exhaust Color	<u>FAIR</u> · Attn																																																																																																														
US EPA	YES · <u>NO</u>																																																																																																														
OPERATION PUMP																																																																																																															
Sound	<u>FAIR</u> · Attn																																																																																																														
Oil leakage	<u>FAIR</u> · Attn																																																																																																														
Power	<u>FAIR</u> · Attn																																																																																																														
COOLING SYSTEM																																																																																																															
Radiator	<u>FAIR</u> · Attn																																																																																																														
Oil Cooler	<u>FAIR</u> · Attn																																																																																																														
TRANSMISSION & TRAVEL																																																																																																															
T/M TYPE	<u>PS</u> · DD																																																																																																														
Transmission	<u>FAIR</u> · Attn																																																																																																														
Travel	<u>FAIR</u> · Attn																																																																																																														
FOOT BRAKE	<u>FAIR</u> · Attn																																																																																																														
PARKING BRAKE	<u>FAIR</u> · Attn																																																																																																														
INTERIOR See Photos. 写真参照																																																																																																															
Operator's Seat	<u>FAIR</u> · <u>Attn</u>	破れあり CUTS																																																																																																													
Inside Cover	<u>FAIR</u> · Attn																																																																																																														
Glasses	<u>FAIR</u> · Attn																																																																																																														
AirCon	A/C · H/C · H only · C only · <u>None</u>																																																																																																														
FRONT & CYLINDERS																																																																																																															
Arm	<u>FAIR</u> · Attn																																																																																																														
Bell crank	<u>FAIR</u> · Attn																																																																																																														
Bucket	<u>FAIR</u> · Attn																																																																																																														
Articulate	<u>FAIR</u> · Attn																																																																																																														
UNDERCARRIAGE : See Photos. 写真参照																																																																																																															
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																														
COMMENT																																																																																																															
<div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING </div> <div style="border: 1px solid black; border-radius: 5px; padding: 5px; margin-bottom: 5px;"> RIDE CONTROL YES · <u>NO</u> </div>																																																																																																															
ATTACHMENTS																																																																																																															
STD BKT	<u>YES</u> · OTHER																																																																																																														
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>																																																																																																														
COMMENT																																																																																																															
左昇降ステップ変形あり LEFT STEP: DEFORMED																																																																																																															
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2																																																																																																														

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。