

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2024/11/26	MAKE	HITACHI	MODEL	CS125		
SERIAL	HCM8AX00K00012369		STAMP	HCM8AX00K00012369			
HR METER	1383	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	-		

ENGINE : MODEL 4JG1 S/N 281060		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE	COMMENT リペイントあり REPAINTED
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil	<input checked="" type="radio"/> FAIR · Attn		
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn		
US EPA	<input checked="" type="radio"/> YES · NO		
OPERATION PUMP			
Sound	<input checked="" type="radio"/> FAIR · Attn		
Oil leakage	<input checked="" type="radio"/> FAIR · Attn		
Power	<input checked="" type="radio"/> FAIR · Attn		
COOLING SYSTEM			
Radiator	<input checked="" type="radio"/> FAIR · Attn		
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	PS · <input checked="" type="radio"/> DD		
Transmission	<input checked="" type="radio"/> FAIR · Attn		
Travel	<input checked="" type="radio"/> FAIR · Attn		
FOOT BRAKE	<input checked="" type="radio"/> FAIR · Attn		
PARKING BRAKE	<input checked="" type="radio"/> FAIR · Attn		
INTERIOR See Photos. 写真参照			
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn		
Inside Cover	<input checked="" type="radio"/> FAIR · Attn		
Glasses	<input checked="" type="radio"/> FAIR · Attn		
AirCon	A/C · H/C · H only · C only · <input checked="" type="radio"/> None		
OTHERS			
Vibratory	<input checked="" type="radio"/> FAIR · Attn		
Watering	<input checked="" type="radio"/> FAIR · Attn	未確認 OPERATION: NOT CHECKED	
Articulate	<input checked="" type="radio"/> FAIR · Attn		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。