INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/11/22	MAKE	KOMATSU	MODEL	PC50FR-2
SERIAL	20071			STAMP	PC50FR-20071
HR METER	5663 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	400G PADS

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	ガタあり SWING: LOOSE
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	ガタあり LOOSE
Boom Cylinder	FAIR・Attn	
Arm	FAIR・Attn	ガタ大 MUCH LOOSE
Arm Cylinder	FAIR・Attn	
BKT	FAIR・Attn	ガタあり LOOSE
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
シューパッド剥がれ多数あり MANY RUBBER PADS: PEELED OFF		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	ブレード下降不可 UNABLE TO LOWER
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi *1
COMMENT		
E/Gフードラッチ破損あり ENGINE HOOD LATCH: BROKEN		
燃料メーター動かない FUEL GAUGE: NOT WORKING		
安全ロックレバー上げたまま保持不可(レバーが勝手に下がる)		
SAFETY LEVER: UNABLE TO KEEP THE LOCKED POSITION		
ホースヒビあり SOME HYDRAULIC HOSES: CRACKED		
右側操作レバーガタあり RIGHT OPERATION LEVER: LOOSE		
*1 配管ペダル固着あり、動作不可 PEDAL: STUCK (UNABLE TO OPERATE)		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。