

INSPECTION SHEET 検品書
 ASPHALT FINISHER アスファルトフィニッシャー

INSPECTION DATE	2024/12/10	MAKE	SUMITOMO	MODEL	HA45W-5
SERIAL	A45A1-0036		STAMP	F40W2-50049	
HR METER	7731	HR	YEAR	YR	
SHOE		TIRE (REAR)	365/80R20	MAX PAVING WIDTH	4500 mm

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
OPERATING SYSTEM		
TRAVEL	<input checked="" type="radio"/> FAIR · Attn	
SCREED(R)	<input checked="" type="radio"/> FAIR · Attn	
SCREED(L)	<input checked="" type="radio"/> FAIR · Attn	
VIBRATION	FAIR · <input checked="" type="radio"/> Attn	故障あり MALFUNCTION
TAMPER	<input checked="" type="radio"/> FAIR · Attn	
SPREADER(R)	<input checked="" type="radio"/> FAIR · Attn	
SPREADER(L)	<input checked="" type="radio"/> FAIR · Attn	
HOPPER(R)	<input checked="" type="radio"/> FAIR · Attn	
HOPPER(L)	<input checked="" type="radio"/> FAIR · Attn	
FEEDER	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
SCREED WIDTH	
MAIN SCREED	1.8 m
WITH AUTO-WIDENER	4.5 m
WITH EXTENSION	m
LEVEL SENSOR	<input checked="" type="radio"/> YES · NO
COMMENT	
プレートとスタンプが違う	
SERIAL NUMBER: NOT EQUAL AT PLATE & STAMP	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。