INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/12/9	MAKE	TCM		MODEL	FD160S-3	
SERIAL	91R03003			STAMP	F53-03003		
HR METER	22342 HR	Odometer	- km		YEAR	YR	
CAB/CNP	CAB / (CNP) / NONE			TIRE SIZE	11.00-20		
MAX LIFTING HEIGHT	2.93 m	(VIEW) / MONO		FORK LENGTH	2400 mm		
FORK SPEC	フォークシフター POSITIONER						

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	にじみあり OIL OOZING
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
OPERATION PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	(PS)・ DD	
Transmission	(FAIR)・ Attn	
Travel	(FAIR)・ Attn	
FOOT BRAKE	(FAIR)・ Attn	
PARKING BRAKE	(FAIR)・ Attn	
INTERIOR	See Photos. 写真参照	
Operator's Seat	(FAIR)・ Attn	破れあり CUT
Inside Cover	FAIR ・ Attn	
Glasses	FAIR ・ Attn	
AirCon	A/C ・ H/C ・ H only ・ C only ・(None)	
HYDRAULICS		
MAST Cylinder	(FAIR)・ Attn	
TILT Cylinder	FAIR ・(Attn)	左右油漏れ小 CYLINDERS: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
左側ステアリングシリンダー傷あり	
LEFT STEERING CYLINDER: SCRATCHED	
フォークシフト用シリンダー左右傷あり	
POSITIONER CYLINDERS: SCRATCHED	
エアクリーナーホース破れあり AIR CLEANER HOSE: CUTS	
ターボ周り油漏れ小 AROUND TURBO: OIL LEAKING	
スロットル周り油漏れ小 AROUND THROTTLE: OIL LEAKING	
燃料計上がらない FUEL GAUGE: MALFUNCTION	
左側フォークシフト動きしぶい	
LEFT CLAW OF POSITIONER: NOT SMOOTH TO MOVE	
スピードメーター動かない SPEED METER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。