

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2024/12/9	MAKE	TOYOTA	MODEL	40-3FD60
SERIAL	403FD60-61073			STAMP	NOT FOUND
HR METER	UNKNOWN	HR	Odometer	1929	km YEAR YR
CAB/CNP	CAB /	CNP	/	NONE	TIRE SIZE 8.25-15
MAX LIFTING HEIGHT	3.0	m	VIEW	MONO	FORK LENGTH 1350 mm
FORK SPEC	ポジショナー POSITIONER				

ENGINE : MODEL		S/N	250631
Oil leakage	<input type="radio"/> FAIR	Attn	
Blow-By	<input type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR	Attn	
Oil	<input type="radio"/> FAIR	Attn	
Exhaust Color	<input type="radio"/> FAIR	Attn	
US EPA	YES	<input checked="" type="radio"/> NO	
OPERATION PUMP			
Sound	<input type="radio"/> FAIR	Attn	
Oil leakage	<input type="radio"/> FAIR	Attn	
Power	<input type="radio"/> FAIR	Attn	
COOLING SYSTEM			
Radiator	<input type="radio"/> FAIR	Attn	
Oil Cooler	<input type="radio"/> FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	<input checked="" type="radio"/> PS	DD	
Transmission	<input type="radio"/> FAIR	Attn	
Travel	<input type="radio"/> FAIR	Attn	
FOOT BRAKE	<input type="radio"/> FAIR	Attn	
PARKING BRAKE	<input type="radio"/> FAIR	Attn	
INTERIOR See Photos. 写真参照			
Operator's Seat	FAIR	<input checked="" type="radio"/> Attn	破れあり HUGE CUT
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	· H/C	· H only · C only · <input checked="" type="radio"/> None
HYDRAULICS			
MAST Cylinder	<input type="radio"/> FAIR	Attn	
TILT Cylinder	<input type="radio"/> FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。