

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

|                 |   |      |          |           |             |      |    |
|-----------------|---|------|----------|-----------|-------------|------|----|
| INSPECTION DATE | 2024/12/9                                     | MAKE | HITACHI  | MODEL     | LX100       |      |    |
| SERIAL          | 41E00148 / DWLX100518463                      |      |          | STAMP     | LX100518463 |      |    |
| HR METER        | 2694  | HR   | Odometer | 5157      | km          | YEAR | YR |
| CAB/CNP         | ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE |      |          | TIRE SIZE | 20.5-25     |      |    |

|  |   |
|--|---|
| <b>ENGINE : MODEL</b> _____ <b>S/N</b> _____ |   |
| Oil leakage                                  | <u>FAIR</u> · Attn                            |
| Blow-By                                      | <u>FAIR</u> · Attn A LITTLE · MIDDLE · SEVERE |
| Sound  | <u>FAIR</u> · Attn                            |
| Oil  | <u>FAIR</u> · Attn                            |
| Exhaust Color                                | <u>FAIR</u> · Attn                            |
| US EPA                                       | YES · <u>NO</u>                               |
| <b>OPERATION PUMP</b>                        |   |
| Sound  | <u>FAIR</u> · Attn                            |
| Oil leakage                                  | <u>FAIR</u> · Attn                            |
| Power  | <u>FAIR</u> · Attn                            |
| <b>COOLING SYSTEM</b>                        |   |
| Radiator                                     | <u>FAIR</u> · Attn                            |
| Oil Cooler                                   | <u>FAIR</u> · Attn                            |
| <b>TRANSMISSION &amp; TRAVEL</b>             |   |
| T/M TYPE                                     | <u>PS</u> · DD                                |
| Transmission                                 | <u>FAIR</u> · Attn                            |
| Travel                                       | <u>FAIR</u> · Attn                            |
| FOOT BRAKE                                   | <u>FAIR</u> · Attn                            |
| PARKING BRAKE                                | <u>FAIR</u> · Attn                            |
| <b>INTERIOR</b> See Photos. 写真参照             |   |
| Operator's Seat                              | <u>FAIR</u> · <u>Attn</u> 破れあり HUGE CUTS      |
| Inside Cover                                 | <u>FAIR</u> · Attn                            |
| Glasses                                      | <u>FAIR</u> · Attn                            |
| AirCon                                       | A/C · <u>H/C</u> · H only · C only · None     |
| <b>FRONT &amp; CYLINDERS</b>                 |   |
| Arm  | <u>FAIR</u> · Attn                            |
| Bell crank                                   | <u>FAIR</u> · Attn                            |
| Bucket                                       | <u>FAIR</u> · Attn                            |
| Articulate                                   | <u>FAIR</u> · Attn                            |

|  |   |
|--|---|
| <b>UNDERCARRIAGE :</b> See Photos. 写真参照                              |   |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 3   |
| <b>COMMENT</b>   |   |
|  |   |
| STEERING TYPE  | <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING |
| RIDE CONTROL   | YES · <u>NO</u>   |
| <b>ATTACHMENTS</b>   |   |
| STD BKT  | <u>YES</u> · OTHER  |
| BLADE  | YES · <u>NO</u> Piping for Tilt                           |
|  | YES · <u>NO</u>   |
| <b>COMMENT</b>   |   |
|  |   |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3   |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。