

INSPECTION SHEET 検品書  
WHEEL LOADER タイヤショベル

INSPECTION DATE	2024/12/12	MAKE	KOMATSU	MODEL	WA380-7
SERIAL	10969		STAMP	WA118-10969	
HR METER	22510	HR	Odometer	68883	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	23.5-25 16PR	
YEAR	YR				

**ENGINE : MODEL** 6D107E-2 **S/N** 26648105

Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

**OPERATION PUMP**

Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

**TRANSMISSION & TRAVEL**

T/M TYPE	PS	DD	
Transmission	FAIR	Attn	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	

**INTERIOR** See Photos. 写真参照

Operator's Seat	FAIR	Attn	破れあり CUT
Inside Cover	FAIR	Attn	
Glasses	FAIR	Attn	*1
AirCon	A/C	H/C · H only · C only · None	

**FRONT & CYLINDERS**

Arm	FAIR	Attn	
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	
Articulate	FAIR	Attn	

**UNDERCARRIAGE :** See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3

**COMMENT**

右Fタイヤ1本パンクあり(オークション後修理予定)  
FRONT RIGHT TIRE: FLAT (REPAIRING AFTER THE AUCTION)  
下周りにじみ大 BOTTOM: MUCH OIL OozING

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL YES · NO

**ATTACHMENTS**

STD BKT YES · OTHER  
BLADE YES · NO Piping for Tilt YES · NO

**COMMENT**

左ドアラッチ不良(閉まらない)  
LEFT DOOR LATCH: MALFUNCTION (UNABLE TO SHUT)  
\*1 F窓クラック大(テープ補修ある)  
\*1 WINDSHIELD: CRACKED (COVERED WITH ADHESIVE TAPES)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。