

INSPECTION SHEET 検品書
MOTOR GRADER グレーダー

INSPECTION DATE	2026/5/18	MAKE	KOMATSU	MODEL	GD500R-2A
SERIAL	20076		STAMP	G50R-20076	
HR METER	E1436	HR	Odometer	E32645	km
YEAR					YR
SCARIFIER	YES	<input checked="" type="radio"/> NO	BLADE	3700 mm	
CAB/CNP	<input checked="" type="radio"/> CAB	/	CNP	/	NONE
TIRE SIZE	14.00-24				

ENGINE : MODEL 6D105-1 S/N 54763	
Oil leakage	FAIR · <input checked="" type="radio"/> Attn *1
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · <input checked="" type="radio"/> NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn キャップ破損あり CAP: DAMAGED
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · <input checked="" type="radio"/> DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · <input checked="" type="radio"/> Attn *2
PARKING BRAKE	FAIR · Attn *3
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY
Operator's Seat	FAIR · Attn 破れあり TORN
Glasses	FAIR · <input checked="" type="radio"/> Attn ドア左側下欠 LOWER LEFT DOOR GLASS: MISSING
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None
HYD. CYLINDER	
For Blade	FAIR · <input checked="" type="radio"/> Attn *4
For Scarifier	FAIR · Attn
Articulate	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · <input checked="" type="radio"/> WORN · UNEVEN WEAR
COMMENT	
配管にじみ多数あり MANY HYDRAULIC PIPES: OIL OOZING	
左右ステアリングシリンダー油漏れ小 STEERING CYLINDERS: OIL LEAKING	
リーニングシリンダー油漏れあり LEANING CYLINDER: OIL LEAKING	
サークル下配管油漏れあり SOME PIPE UNDER CIRCLE: OIL LEAKING	
CABドア右ラッチかからない RIGHT DOOR LATCH: MALFUNCTION	
左右サイドカバー欠 SIDE COVERS: MISSING	
オイルパンへコミあり OIL PAN: DENT	
左側サークルリフト動作不良(少しだけピクッと動くが上下できない)	
LEFT CIRCLE LIFT: MALFUNCTION	
(UNABLE TO MOVE UP or DOWN EVEN A LITTLE TWITCHING)	
HRメーター、走行メーターストップ HR METER & ODOMETER: STOPPED	
*1 ブロックの間から油漏れ小	
*1 CONNECTING PART BETWEEN HEAD COVER AND ENGINE BLCOK: OIL LEAKING	
*2 効かない、左右配管破損あり	
*2 BRAKE: MALFUNCTION, HYDRAULIC HOSES: BROKEN,	
*3 レバー下ろすとブザー音あり	
*3 WARNING SOUNDS: ON DURING RELEASING THE BRAKE	
*4 スライド用シリンダー油漏れ小 SLIDE CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。