

INSPECTION SHEET 検品書
OTHER その他

| | | | | | |
|-----------------|--|----------|-------|-----------|----|
| INSPECTION DATE | 2024/12/12 | CATEGORY | CABIN | | |
| MAKE | UNKNOWN | | MODEL | UNKNOWN | |
| SERIAL | NOT FOUND | | STAMP | NOT FOUND | |
| HR METER | HR | Odometer | km | YEAR | YR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | SHOE | TIRE | |

| | | | | | |
|-------------|-------------|----------------------------|---------------|-------------|--|
| ENGINE | MODEL | S/N | | | |
| Oil leakage | FAIR ・ Attn | | Oil | FAIR ・ Attn | |
| Blow-By | FAIR ・ Attn | A LITTLE ・ MIDDLE ・ SEVERE | Exhaust Color | FAIR ・ Attn | |
| Sound | FAIR ・ Attn | | EPA | YES ・ NO | |

| | | |
|-----------|-------------|--|
| CONDITION | FAIR ・ Attn | |
| | | |

UNDERCARRIAGE : See Photos. 写真参照

| | | |
|--|---|--|
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 5 | |
|--|---|--|

COMMENT

未使用 UNUSED

| | | |
|--|--|--|
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | |
|--|--|--|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。