

INSPECTION SHEET 検品書  
OTHER その他

INSPECTION DATE	2024/12/12	CATEGORY	BUCKET for 0.7m3			
MAKE	UNKNOWN			MODEL	UNKNOWN	
SERIAL	NOT FOUND			STAMP	NOT FOUND	
HR METER	HR	Odometer	km	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	TIRE		

ENGINE	MODEL	S/N
Oil leakage	FAIR ・ Attn	Oil FAIR ・ Attn
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE Exhaust Color FAIR ・ Attn
Sound	FAIR ・ Attn	EPA YES ・ NO

CONDITION	FAIR ・ Attn	

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	5	
--	---	--

**COMMENT**

未使用 UNUSED

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
--	--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。