INSPECTION SHEET 検品書 OTHER その他

							• •							
INSPECTIO	ON DATE	N DATE 2024/12/12			CATEGORY			TIRE for WA100-7						
MAKE	UNKNOWN						MOD	EL		UNKNOWN				
SERIAL	NOT FOUND						STAN	ИP	NOT FOUND					
HR METER	HR Odometer								km YEAR YR				YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE SHO								TIRE 16.9-24			6.9-24		
ENGINE	MODEL							1						
Oil leakage	FAIR · Attn						Oil		FAIR • Attn					
Blow-By	FAIR · Attn A LITTLE • MIDDLE • SEVERE						Exhaust	Color	FAIR • Attn					
Sound	FAIR · Attn						EPA	4	YES • NO					
CONDITION FAIR - Attn														
LINDEDOADDYAGE. C. Di														
UNDERCARRIAGE: See Photos. 写真参照														
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 5														
COMMENT 未使用 UI														
ホイール付き W/RIM														

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)