

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/12/19	MAKE	CAT	MODEL	E70
SERIAL	3CG09225		STAMP	UNREADABLE	
HR METER	E6514	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	450G	

ENGINE : MODEL 4D31 S/N 596289	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタ大 SWING: MUCH LOOSE
Travel	FAIR · Attn *1
INTERIOR See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり TORN
Inside Cover	FAIR · Attn 全体腐食、穴あり CORRODED & HUGE HOLES
Glasses	FAIR · Attn *2
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn *3
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
COMMENT	
穴あり MUCH HUGE HOLES	
HRメーターストップ HR METER: STOPPED	
ヒーター不良 HEATER: MALFUNCTION	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER / FORK GRAB
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
サイドカバー取付部破損あり	
SOME LEFT SIDE COVER HINGE: BROKEN	
CABドア変形あり、閉まらない DOOR: DISTORTED, UNABLE TO SHUT	
逆レバー OPOSITION OPERATION LEVER	
キーシリンダー動き悪い KEY CYLINDER: HEAVY, NOT SMOOTH TURNING	
CAB取り付け補修あり LOWER PART OF CAB: FIXING WITH WIRES	
ボディへコミあり BODY: MUCH DENT	
*1 左右走行モーター油汚れあり TRAVEL MOTORS: OIL STAINS	
*2 F下部、ドアガラス欠	
*2 LOWER WINDSHIELD & SOME DOOR GLASS: MISSING	
*3 上げる動作遅い(低回転時動かない)	
*3 SLOW MOVING FOR GOING UP (NOT MOVING WITH LOW ENGINE SPEED)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。