

**INSPECTION SHEET 検品書**  
**WHEEL EXCAVATOR タイヤバックホー**

INSPECTION DATE	2024/3/25	MAKE	KOMATSU	MODEL	PW200-1
SERIAL	10096		STAMP	PW2001-10096	
HR METER	6831	HR Odometer	-	km YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	10.00-20	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input type="radio"/> FAIR · Attn	
Blow-By	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	A LITTLE · <input checked="" type="radio"/> MIDDLE · SEVERE
Sound	<input type="radio"/> FAIR · Attn	
Oil	<input type="radio"/> FAIR · Attn	
Exhaust Color	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	白煙あり WHITE FUMES
US EPA	YES · <input checked="" type="radio"/> NO	
<b>MAIN PUMP</b>		
Sound	<input type="radio"/> FAIR · Attn	
Oil leakage	<input type="radio"/> FAIR · Attn	油污れあり OIL STAINS
Power	<input type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input type="radio"/> FAIR · Attn	
Oil Cooler	<input type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Swing	<input type="radio"/> FAIR · Attn	ガタあり SWING: LOOSE
Travel	<input type="radio"/> FAIR · Attn	
<b>INTERIOR See Photos. 写真参照</b>		
Operator's Seat	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn	破れあり TORN
Inside Cover	<input type="radio"/> FAIR · Attn	
Glasses	<input type="radio"/> FAIR · Attn	
AirCon	A/C · <input checked="" type="radio"/> H/C · H only · C only · None	
<b>BOOM / ARM / BKT</b>		
Boom	<input type="radio"/> FAIR · Attn	
Boom Cylinder	<input type="radio"/> FAIR · Attn	
Arm	<input type="radio"/> FAIR · Attn	
Arm Cylinder	<input type="radio"/> FAIR · Attn	
BKT	<input type="radio"/> FAIR · Attn	
BKT Cylinder	<input type="radio"/> FAIR · Attn	

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
BKT	STD / SLOPE / NARROW / SKELETON · <input checked="" type="radio"/> OTHER (MAGNET)
Lever	LONG · <input checked="" type="radio"/> WRIST
Multi	MULTI · 2 · <input checked="" type="radio"/> NO
ARM-CRANE	YES · <input checked="" type="radio"/> NO
BLADE	YES · <input checked="" type="radio"/> NO
OFFSET	YES · <input checked="" type="radio"/> NO
OFFSET Cylinder	<input type="radio"/> FAIR · Attn
Piping	<input checked="" type="radio"/> YES · NO Breaker only · <input checked="" type="radio"/> Multi
OUTRIGGERS COND.	<input type="radio"/> FAIR · Attn
<b>COMMENT</b>	
ワンタッチ付 W/ONE-TOUCH	
後付けHRメーター RETROFITTED HR METER: 539HR	
A/Cベルト欠 A/C: NO BELT	
フットブレーキ不良 FOOT BRAKE: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。