

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/3/25	MAKE	CAT	MODEL	345CL
SERIAL	CAT0345CLRFN00176		STAMP	CAT0345CLRFN00176	
HR METER	2160 / 2283	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	SHOE		600G	

<b>ENGINE : MODEL</b>	C13	<b>S/N</b>	MHX02204
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	<u>YES</u> · NO		

<b>MAIN PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		

<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		

<b>OPERATING SYSTEM</b>			
Swing	<u>FAIR</u> · Attn	ガタあり SWING: LOOSE	
Travel	<u>FAIR</u> · Attn		

<b>INTERIOR</b> See Photos. 写真参照			
Operator's Seat	<u>FAIR</u> · Attn		
Inside Cover	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn	Fひび割れあり WINDSHIELD: CRACKED	
AirCon	<u>A/C</u> · H/C · H only · C only · None		

<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · <u>Attn</u>	クラック、補修あり CRACKED, REPAIRED	
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

<b>COMMENT</b>	

BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <u>WRIST</u>
Multi	<u>MULTI</u> · 2 · NO
ARM-CRANE	YES · <u>NO</u>
BLADE	YES · <u>NO</u>
OFFSET	YES · <u>NO</u>
OFFSET Cylinder	<u>FAIR</u> · Attn
Piping	<u>YES</u> · NO Breaker only · <u>Multi</u> 5

<b>COMMENT</b>	
3段ブーム 3-SECTION BOOM	
作業半径: 24.1m OPERATING RADIUS: 24.1m	
アタッチメントなし WITHOUT ATTACHMENT	
付属品: 3段ブーム用台座	
FIXING STAND FOR 3-SECTION BOOM AS SPARE	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。