# INSPECTION SHEET 検品書
## DUMP TRUCK ダンプ

| | | | |
|---|---|---|---|
| INSPECTION DATE | 2025/1/9 | CATEGORY | (ON-ROAD DUMP) ・ OFF-ROAD DUMP |
| MAKE | ISUZU | MODEL | FRR90 |
| SERIAL | FRR90-7147321 | STAMP | FRR90-7147321 |
| HR METER | 2799 HR | ODOMETER | 47050 km |
| TIRE SIZE | 225/80R17.5 | YEAR | YR |

| ENGINE : MODEL | S/N | |
|---|---|---|
| Oil leakage | (FAIR) ・ Attn | |
| Blow-By | (FAIR) ・ Attn | A LITTLE ・ MIDDLE ・ SEVERE |
| Sound | (FAIR) ・ Attn | |
| Oil | (FAIR) ・ Attn | |
| Exhaust Color | (FAIR) ・ Attn | |
| US EPA | YES ・(NO) | |

| OPERATION PUMP | | |
|---|---|---|
| Sound | (FAIR) ・ Attn | |
| Oil leakage | (FAIR) ・ Attn | |
| Power | (FAIR) ・ Attn | |

| COOLING SYSTEM | | |
|---|---|---|
| Radiator | (FAIR) ・ Attn | |
| Oil Cooler | (FAIR) ・ Attn | |

| TRANSMISSION & TRAVEL | | | | |
|---|---|---|---|---|
| T/M TYPE | AT ・(MT) | | No. OF GEARS | 6 GEARS |
| Transmission | (FAIR) ・ Attn | | | |
| 4WD | 4WD ・(2WD) | | | |
| Travel | (FAIR) ・ Attn | | | |
| Articulate | (FAIR) ・ Attn | | | |
| FOOT BRAKE | (FAIR) ・ Attn | | | |
| PARKING BRAKE | (FAIR) ・ Attn | | | |

| INTERIOR See Photos. 写真参照 | | |
|---|---|---|
| Operator's Seat | (FAIR) ・ Attn | |
| Inside Cover | (FAIR) ・ Attn | |
| Glasses | (FAIR) ・ Attn | |
| AirCon | (A/C) ・ H/C ・ H only ・ C only ・ None | |

| MAIN FRAME | | |
|---|---|---|
| MAIN FLAME | (FAIR) ・ Attn | |

| VESSEL | | |
|---|---|---|
| MAKE | 極東開発工業 KYOKUTO | |
| VESSEL | (FAIR) ・ Attn | |
| REAR GATE TYPE | NORMAL ・(L-GATE (FLAT)) | |
| REAR GATE | (FAIR) ・ Attn | |

| UNDERCARRIAGE: See Photos. 写真参照 | |
|---|---|
| **RUST** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |

**COMMENT**

MODEL: DD04-53A S/No. 19A08R008Y

最大積載量 MAXIMUM LOAD: 3350kg

| **RUST of BODY** (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 |
|---|---|

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。