

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

INSPECTION DATE	2025/1/17	MAKE	HITACHI	MODEL	ZX160LC-3
SERIAL	HCM1T100K00011666		STAMP	HCM1T100K00011666	
HR METER	10246	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	

<b>MAIN PUMP</b>	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn

<b>COOLING SYSTEM</b>	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn

<b>OPERATING SYSTEM</b>	
Swing	FAIR · Attn
Travel	FAIR · Attn

<b>INTERIOR</b> See Photos. 写真参照	
Operator's Seat	FAIR · Attn 破れあり TORN
Inside Cover	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None

<b>BOOM / ARM / BKT</b>	
Boom	FAIR · Attn パッチあり PATCHED
Boom Cylinder	FAIR · Attn
Arm	FAIR · Attn
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

<b>COMMENT</b>	
両側ピンブッシュひび割れあり SOME PIN BUSHES: CRACKED	
シューリンククラックあり SOME TRACK LINKS: CRACKED	

BKT	STD / SLOPE / NARROW / SKELETON (OTHER)
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5

<b>COMMENT</b>	
アタッチメント: 回転式グラップル ATTACHMENT: ROTATABLE GRAPPLE	
グラップル開かない GRAPPLE: UNABLE TO OPEN	
両側サイドカバーへコミ大 SIDE COVERS: MUCH DENT	
両側サイドカバー前カバーロック部曲がりあり	
FRONT LOCK PARTS OF SIDE COVERS: BENT	
バックモニター不良 BACK MONITOR: MALFUNCTION	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。