

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/4/1	MAKE	CAT	MODEL	D7G
SERIAL	Z45W00413		STAMP	45W00413	
HR METER	1971	HR	SHOE	860LGP	YEAR 1984 YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE	

ENGINE : MODEL		S/N
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
OPERATION PUMP		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
COOLING SYSTEM		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	PS · <input checked="" type="radio"/> DD	DIFF. STEERING YES · <input checked="" type="radio"/> NO
Transmission	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · <input checked="" type="radio"/> DIRTY	
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	破れあり CUTS
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	A/C · H/C · <input checked="" type="radio"/> H only · C only · None	
BLADE & CYLINDERS		
BLADE	<input checked="" type="radio"/> FAIR · Attn	
CYLD.(R)	<input checked="" type="radio"/> FAIR · Attn	*1
CYLD.(L)	<input checked="" type="radio"/> FAIR · Attn	*1
TILT CYLD	<input checked="" type="radio"/> FAIR · Attn	*1
ANGLE CYLD	<input checked="" type="radio"/> FAIR · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper MULTI · S/S Shanks PCS </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> Ripper CYLD. FAIR · Attn </div> <div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> EQUALIZER BAR FAIR · Attn </div>			
COMMENT			
左右サイドカバー欠 SIDE COVERS: MISSING			
*1 サビ、メッキ剥がれあり RUSTY, COATING: PEELED			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 5px;"> RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) </div>			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。