

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/2/13	MAKE	YANMAR	MODEL	SV08-1
SERIAL	13575B			STAMP	13575B
HR METER	1138	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>			SHOE	180R

ENGINE : MODEL 2TE67L S/N 06542

Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	<u>YES</u> · NO	

MAIN PUMP

Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	

COOLING SYSTEM

Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	

OPERATING SYSTEM

Swing	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR · <u>Attn</u>	破れあり CUT
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	

BOOM / ARM / BKT

Boom	<u>FAIR</u> · Attn	
Boom Cylinder	<u>FAIR</u> · Attn	
Arm	<u>FAIR</u> · Attn	
Arm Cylinder	<u>FAIR</u> · Attn	
BKT	FAIR · <u>Attn</u>	2ヶ所割れあり MUCH CRACKED
BKT Cylinder	<u>FAIR</u> · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

可変脚仕様 VARIABLE WIDTH UNDERCARRIAGE

BKT (STD) / SLOPE / NARROW / SKELETON / OTHER ()

Lever LONG · WRIST

Multi MULTI · 2 · NO

ARM-CRANE YES · NO

BLADE YES · NO

OFFSET YES · NO

OFFSET Cylinder FAIR · Attn

Piping YES · NO Breaker only · Multi

COMMENT

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。