

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/10	MAKE	CAT	MODEL	345B- II
SERIAL	NO PLATE		STAMP	CAT0345BKAMD00353	
HR METER	8791	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL						3176		S/N		7ZR08891	
Oil leakage		(FAIR)	Attn								
Blow-By		(FAIR)	Attn		A LITTLE ・ MIDDLE ・ SEVERE						
Sound		(FAIR)	Attn								
Oil		(FAIR)	Attn								
Exhaust Color		(FAIR)	Attn								
US EPA		(YES)	NO								
MAIN PUMP											
Sound		(FAIR)	Attn								
Oil leakage		(FAIR)	Attn								
Power		(FAIR)	Attn								
COOLING SYSTEM											
Radiator		(FAIR)	Attn								
Oil Cooler		(FAIR)	Attn								
OPERATING SYSTEM											
Swing		(FAIR)	Attn								
Travel		(FAIR)	(Attn) *1								
INTERIOR See Photos. 写真参照											
INTERIOR COND.		CLEAN	・ (FAIR) ・		DIRTY						
Operator's Seat		(FAIR)	Attn								
Glasses		(FAIR)	Attn								
AirCon		(A/C)	・ H/C		・ H only		・ C only		・ None		
BOOM / ARM / BKT											
Boom		(FAIR)	Attn								
Boom Cylinder		(FAIR)	(Attn)		右油漏れ小 RIGHT CYLINDER: OIL LEAKING						
Arm		(FAIR)	(Attn)		ガタ、ピン補修あり LOOSE, PIN: REPAIRED						
Arm Cylinder		(FAIR)	(Attn)		油漏れあり OIL LEAKING						
BKT		(FAIR)	Attn								
BKT Cylinder		(FAIR)	Attn								

UNDERCARRIAGE :						See Photos. 写真参照								
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)												3		
COMMENT														
ピンブッシュ摩耗小 PIN BUSHES: WORN														
BKT		(STD)	SLOPE / NARROW / SKELETON / OTHER()											
Lever		LONG	・ (WRIST)											
Multi		MULTI	・ 2		(NO)									
ARM-CRANE		YES	・ (NO)											
BLADE		YES	・ (NO)											
OFFSET		YES	・ (NO)											
OFFSET Cylinder		FAIR	・ Attn											
Piping		YES	・ (NO)		Breaker only		・ Multi							
COMMENT														
ボディ底板2ヶ所欠 2 PIECES OF UNDER COVERS: MISSING														
ボディ変形多数あり BODY: DEFORMED														
*1 右足:低速時何かが引っ掛かったような足の回転になり真っすぐに進まない														
*1 RIGHT TRACK: CAUGHT ON SOMETHING DURING TRAVELING WITH LOW GEAR														
(UNABLE TO TRAVEL STRAIGHT)														
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)												1		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。