

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/2/17	MAKE	SUMITOMO	MODEL	SH350HD-5
SERIAL	?????????MH3343 (PLATE: BROKEN)			STAMP	SMT350A5L00MH3343
HR METER	28481	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL		6HK1	S/N	568845
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	*1	
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn	にじみあり OIL OOZING	
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn	H/Lにならない UNABLE TO SHIFT IN THE HIGH GEAR	
INTERIOR See Photos. 写真参照				
Operator's Seat	FAIR	Attn	破れ大、汚れ大 TORN, DIRTY	
Inside Cover	FAIR	Attn	汚れあり DIRTY	
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BOOM / ARM / BKT				
Boom	FAIR	Attn	クラックあり CRACKED	
Boom Cylinder	FAIR	Attn	左右油漏れあり CYLINDERS: OIL LEAKING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	
BKT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	油漏れあり OIL LEAKING	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
アタッチメント: マグネット(フォーク付) ATTACHMENT: MAGNET-FORK	
エレベータCAB ELEVATOR CAB	
電気系統異常、E/G系統異常、冷却水補給表示あり	
WARNINGS DISPLAY FOR	
AN ELECTRIC SYSTEM, ENGINE, & REFILLING COOLANT	
ウエイト外れ、マグネット外れあり	
COUNTER WEIGHT & MAGNET: COME OFF	
下周り油漏れあり BOTTOM: OIL LEAKING	
*1 ポンプ周り、ホース油漏れあり	
*1 AROUND PUMP & SOME HOSES: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。