

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/7	MAKE	KUBOTA	MODEL	U-40-6E
SERIAL	KBCDZ46APL3F32442		STAMP	KBCDZ46APL3F32442	
HR METER	1452	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	350G PADS	

ENGINE : MODEL		S/N	7LJ5400
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり CUT
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only ・ C only ・ None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
COMMENT			
BKT	STD	SLOPE	NARROW / SKELETON / OTHER ()
Lever	LONG	WRIST	
Multi	MULTI	2	NO
ARM-CRANE	YES	NO	*1
BLADE	YES	NO	
OFFSET	YES	NO	
OFFSET Cylinder	FAIR	Attn	
Piping	YES	NO	Breaker only ・ Multi
COMMENT			
排気温度計センサー故障、ワーニングランプ点灯あり			
EXHAUST GAS TEMPERATURE SENSOR: MALFUNCTION,			
WARNING LAMP: ON			
*1 クレーン荷重センサー故障あり LOAD SENSOR: MALFUNCTION			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。